

Molar Eruption

Please review scans and models that are having bands, crowns, or ROC's placed on them. If tissue is covering the teeth, or if the teeth are not fully erupted, we cannot guarantee the fit of these appliances. It may be better to utilize different teeth for anchorage. Generally, a panoramix X-ray needs to be viewed to see if the second deciduous molars can be utilized. In the event that we are asked to proceed with indirectly fitting bands/crowns on less-than-fully-erupted teeth, we will issue a "No Guarantee" on the fit of the requested appliance. If you have any questions regarding this, you can reach our customer Care team.

